

Oil Field Environmental Incident Summary

Incident: 20150327152820 **Date/Time of Notice:** 03/27/2015 15:28
Responsible Party: CONTINENTAL RESOURCES, INC.
Well Operator: CONTINENTAL RESOURCES, INC.
Well Name: WINCHESTER 43-8SH
Field Name: CEDAR HILLS **Well File #:** 27121
Date Incident: 3/26/2015 **Time Incident:** 15:00 **Facility ID Number:**
County: BOWMAN **Twp:** 132 **Rng:** 106 **Sec:** 8 **Qtr:**
Location Description: Spill stayed on flowline ROW in pasture.

Submitted By: Patrick Skillestad **Received By:**
Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels
Brine	6	Barrels	6	Barrels	6	barrels

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/13/2015 **Clean Up Concluded:** 4/10/2015

Risk Evaluation:

None

Areal Extent:

20 feet x 30 feet

Potential Environmental Impacts:

Topsoil on flowline ROW.

Action Taken or Planned:

All contaminated soil was removed and disposed of. Flowline was repaired.

Wastes Disposal Location: Little Missouri Special Landfill

Agencies Involved:

Updates

Date: 3/27/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas in a pasture along a pipeline ROW. Followup is necessary.

Date: 4/7/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 14:56 p.m. The weather was cloudy, 56 °F, with the wind from the northwest at 5-10 mph. The pipeline right of way is disturbed from the south side of pad going southwest for a couple hundred yards. It has been leveled off. The pipeline has been repaired. A depression area just on south edge of pad has been dug out. The pipeline right of way crosses a gumbo area. The impacted soil is piled on a tarp next to the pad. More followup required. 46.27001, -103.95483

Date: 4/21/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I talked to the supervisor about this spill during our discussion on the second spill. This spill occurred on the south side of pad. While repairing this line, they replaced the first few sections of pipe with different line. The soil from this spill will be hauled away with the new impacted soil. Further followup will be done, along with addressing the second spill.

Date: 6/3/2016 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on 4/26/16 at 11:19 am. The soil stockpiles have been removed, and the vegetation in the impact area appears healthy. No further action is warranted.

Date: 6/6/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.